

Technical Data Sheet

July 2025 - This data sheet supersedes all previous issues.

Always use correct Personal Protective Equipment.

SPRAY KLEEN



DESCRIPTION

Spray Kleen is a versatile cleaner designed for a variety of uses around the house, workshop or for commercial cleaning purposes (bathroom tiles, shower walls and floors etc). Spray Kleen will remove smoke stains on ceilings, mould and mildew. It is a completely water soluble, mildly alkaline cleaner that contains a blend of water softening detergents.



PROPERTIES

Product Type:	Concentrate ready for dilution
Colour:	Opaque Blue/green
Density:	Approx. 1.00 kg/L
Solubility in Water:	Soluble



DILUTION

Heavily soiled substrate:	10 parts water to 1 part Spray Kleen
Medium soiled substrate:	20 parts water to 1 part Spray Kleen
Smoke stains:	20 parts water to 1 part Spray Kleen
Low soiled substrate:	40 parts water to 1 part Spray Kleen



APPLICATION

Substrates

Spray Kleen is an all-purpose cleaner with many household and commercial uses.

- Home bathroom tiles, shower walls, appliances, counter tops, linoleum floors etc
- Car all hard interior surfaces, great on windows.
- Workshop benches, floors, windows.

Please note: For best practise use a small test area first to confirm desired result.



Technical Data Sheet

July 2025 - This data sheet supersedes all previous issues.

Always use correct Personal Protective Equipment.



DIRECTIONS FOR USE

Low Soiling:	 Spray onto a clean cloth, so that the cloth is moist. Wipe the surface with the cloth. Wipe the surface with a second dry cloth before it dries. Replace the cloth as it becomes wet or dirty.
Mildew or Mould:	Spray on and leave for 5-10 minutes.Wipe off with a wet cloth.
Windows or Glass:	 Spray onto a clean cloth, so that the cloth is moist. Wipe the surface with the cloth. Wipe the surface with a second dry cloth before it dries. Make sure all residue has been removed to prevent smears or streaks Replace the cloth as it becomes wet or dirty.
Smoke Stains:	Spray or wipe on leaving for 10 minutes.Wipe off with a wet cloth.
Mud or grime from rubber or plastics on commercial equipment:	- Spray on and hose off with water.



HEALTH & SAFETY

ALWAYS READ THE SAFETY DATY SHEET (SDS) PRIOR TO USE. Observe the precautionary notices displayed on the container.

Transport & Storage

Sizes: 4L, 20L	
----------------	--

No warranty either expressed or implied is made by RALI in this document, which is a technical data information sheet. The description of the product and its properties is for the sole purpose of identifying the product and does not constitute a warranty that the product or its properties shall conform to that description, nor is the description of the product and its properties a warranty by RALI that the goods are suitable for a particular purpose. Do not apply paint if relative humidity is above 85% or temperature is within 3 deg C of Dew Point being the MPT or **M**inimum Paint **T**emperature